



Remote display software for InteliLite 4 controllers

SW version 1.2.0

1 General information	2
2 Changes in the version 1.2.0	3
3 Changes in the version 1.1.0	4
4 Changes in the version 1.0.1	5
5 Notes	6

Copyright © 2022 ComAp a.s.
Written by Michal Slavata
Prague, Czech Republic
ComAp a.s., U Uranie 1612/14a,
170 00 Prague 7, Czech Republic
Tel: +420 246 012 111
E-mail: info@comap-control.com, www.comap-control.com

1 General information

1.1 Version information

Mirroring of master's LBOs state.

1.2 Clarification of Notation

Note: This type of paragraph calls the reader's attention to a notice or related theme.

IMPORTANT: This type of paragraph highlights a procedure, adjustment etc., which can cause a damage or improper function of the equipment if not performed correctly and may not be clear at first sight.

WARNING: This type of paragraph highlights a procedure, adjustment etc., which can cause a damage or improper function of the equipment if not performed correctly and may not be clear at first sight.

Example: This type of paragraph contains information that is used to illustrate how a specific function works.

2 Changes in the version 1.2.0

2.1 New features

- > Mirroring of master's LBOs state
 - >> Physical state of remote display's LBOs is the same like on master controller

3 Changes in the version 1.1.0

3.1 New features

- > Support of new version of InteliLite4 controller
 - >> Support of HW 1.1
 - >> Support of FW 1.2.0

4 Changes in the version 1.0.1

4.1 Repairs

- > General bugfixing
 - >> Making connection stability and software compatibility improvements

5 Notes

5.1 Document history

Revision number	Related sw version	Date	Author
3	1.2.0	7.12.2022	Michal Slavata
2	1.1.0	7.12.2021	Michal Slavata
1	1.0.1	22.3.2021	Čeněk Pěč